

# **KLEIBERIT 782.5 Supramelt**

# **Fields of application**

Edging of sheet material with:

- ABS-, PMMA-, PVC- and PP-edges (with
- suitable bonding agent)
- Paper-edges
- Veneer and solid wood edges

## **Advantages**

• Delivered in cartridges with protection film and granulates

## Properties of the bond

- Heat resistance approx. 100°C according to the edge (the bond withstands temperatures of up to 120°C in a drying tunnel for a short period)
- Cold resistance according to the edge down to approx. -30℃
- Good resistance to water (important when staining or bleaching veneer edges)
- Good ageing resistance

## Properties of the adhesive

Base:EVA CopolymerSpecific gravity:approx. 0.96 g/cm³Colour:transparent yellowishViscosityBrookfield HBTD, Sp. 27/10 rpm:Brookfield HBTD, Sp. 27/10 rpm:approx. 36,000mPa·sMelting index according to DIN 53 735(MFI 150/2,16):approx. 105 g/10 min

### Softening point (ring + ball): approx. 101℃

Melting time:	2-5 min

# Working temperature:

	Above 200℃. For solid edges
	or difficult plastic edges up to
	230℃ (short period only).
	Low temperatures can cause faulty
	bonding – ensure that the
	temperature is correctly set.
Delivery form:	1. Cartridge $arnothing$ 63 $\pm$ 0.5 mm
	Length 80 $\pm$ 2 mm
	2. Granulate
Identification:	Identification not required
	according to EU regulations
	(see our safety data sheet)

When hotmelt adhesives are melted and applied, vapours are set free and an unpleasant odour can occur even if the recommended working temperature has been observed. Moreover, if the prescribed working temperature is exceeded over a longer period, harmful decomposition products can develop. Precautions should be taken to eliminate the vapours, e.g. by using a suitable ventilation system.

## Feed rate

 Depending on edging material between 18 - 35 m/min. Different speeds are possible depending on installation equipment.

## Processing

The substrates for edge bonding have to be processed at exact right angles and should be free from dust. Boards and edges have to be conditioned to room temperature. The most favourable moisture content of the wood is 8-10%. Room temperature should not be lower than 18°C. Draughts have to be avoided.

Melting time: 2 - 5 min Working temperature: above 200℃

When processing wood types which are difficult to bond, the working temperature can be briefly raised to 230°C.

Temperature control is particularly important when bonding solid wood edges. For long and thick items, work within the higher temperature range. Lower temperatures lessen the wetting of the edge. The amount of adhesive and pressure applied should be set so that the beads applied are squeezed to form an adhesive layer all-over the surface to be bond and the adhesive pearls slightly at the edge. This can be checked best with a transparent test edge.

Tips for solid wood bonding:

- For solid wood edges select plain, mature wood which does not tend to sag
- Wood edges with standing year rings for the glue line provide optimal strength
- Prepare the carrier material carefully



# **KLEIBERIT 782.5 Supramelt**

- Chipboard should not have any rough cut surfaces
- Adjust the press rollers to somewhat less than the edge thickness.

### Further processing:

The finished material can be processed further immediately following bonding (Sawed, milled, planed, etc.). Because the characterisics of edging materials can vary, individual testing is essential!

## Cleaning

Observe the manufacturer's recommendations when cleaning tools and application plant.

## Packaging

KLEIBERIT SK 782.5:

Delivery carton with 45 cartridges, approx. 11 kg Paper bag, 20 kg net

### Storage

KLEIBERIT 782.5 Supramelt can be stored for 2 years. Keep cool and dry.

Version 09/05/2018 XI; replaces previous versions

### Adhesive and Waste Disposal

#### Waste Code 080410

Our containers are made of recyclable material. Well drained containers can be recycled.

### Service

Our application department may be consulted at any time without obligation. The statements made herein are based on our experience gained to date. They are to be considered as information without obligation. Please test and establish for yourself the suitability of our products for your particular purposes. No liability exceeding the value of our product can be derived from the foregoing statements. This also applies to the technical consultancy service which is rendered free of charge and without obligation.

KLEIBERIT AUSTRALIA Pty Limited, Unit 36, 42-46 Wattle Road Brookvale NSW 2100, Phone: +61 2 9907 1411, Fax: +61 2 9938 4091 Email: info.australia@kleiberit.com